CERTIFICATE OF COMPLIANCE

Certificate Number R-R13976

Report Reference R13976-19910125

Date 2022-November-28

Issued to: Hanchett Entry Systems Inc, DBA Securitron Magnalock

Corp

10027 S 51st St, Suite 102 PHOENIX AZ 85044-5219 US

This is to certify that representative samples of

AUXILIARY LOCKS

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: ANSI/UL 10C Positive Pressure Fire Tests of Door

Assemblies

ANSI/UL 10BFire Tests of Door Assemblies

CAN/ULC-S104-15-R2020 Standard Method for Fire Tests

of Door Assemblies

Additional Information: See the UL Online Certifications Directory at

https://ig.ulprospector.com for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.

Olbrah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, pleas contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/



CERTIFICATE OF COMPLIANCE

Certificate Number

Report Reference R13976-19910125

Date 2022-November-28

R-R13976

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Auxiliary Lock Series M32 and M62 with suffix letters B, D, BD, or F, for installation on Listed firedoor frames and/or Classified swinging firedoors rated up to and including 3 hrs. Auxiliary Locks Series M82, M68, M62, M38, M34, M34RB, SAM, SAMSC, SAM2-12 and SAM2-24 with suffix letters C, DV, S, L, F or G, for installation on Listed firedoor frames and/or Classified swinging firedoors rated up to and including 1 hr

Octoah Jennings-Course

Deborah Jennings-Conner, VP Regulatory Services

UL LLC

(UL)